

2.2.1 Remedy when 00002000 has occurred

CAUSE OF THE ERROR

The reading of steps on the CR scale has been skipped during printing. Skipped reading occurred 100 times during a job. The cause of the skipped reading is as follows.

- Unexpected causes:
Paper jam, vibration, etc.
- Underlying causes:
Attachment of mist on the scale, fold on the scale, foreign object on the scale, etc.

REMEDY

