




DECAL APPLICATION - CENTER HINGE METHOD.
 BE SURE SURFACE IS CLEAN. ALCOHOL AND WATER MIXTURE IS GOOD FOR PREPARING SURFACE.
 NEVER USE PAINT THINNER AS CLEANING AGENT.
 DO NOT APPLY IN DIRECT SUNLIGHT. BEST TEMP IS BETWEEN 60 AND 85 DEGREES




1) MEASURE AND TAPE DECAL IN PLACE WITH MASKING TAPE.




4) STARTING AT CENTER "HINGE", SQUEEGEE IN UP & DOWN MOTION WORKING OUT TO LEFT EDGE. GO SLOWLY AND APPLY EVEN PRESSURE.




2) APPLY TAPE FOR CENTER "HINGE". REMOVE CORNER TAPE



5) REMOVE CENTER "HINGE" TAPE, PEEL BACK TOP PAPER INCLUDING DECAL. REMOVE REMAINING BACKING PAPER. SQUEEGEE FROM CENTER TO RIGHT END.



3) PEEL BACK TOP PAPER LAYER INCLUDING DECAL.. TEAR OFF BACKING PAPER NEAR CENTER "HINGE"



6) SLOWLY PEEL BACK TOP PAPER AT SHARP ANGLE, LEAVING DECAL STUCK IN PLACE